

Series MX-PRO proportional pressure regulator and proportional flow valve

Regulator and valve ports (standard and Manifold): G1/2 Regulator: with built-in pressure gauge or G1/8 threaded ports Valve: without pressure gauge



Series MX-PRO electronic proportional pressure regulator is the result of combining advanced technology of Series K8P electronic proportional micro regulator, with reliability and high performance of Series MX2 modular regulators. This new regulator ensures high precision in pressure regulation, high flow rate and low consumption. Moreover, it can take the most of Series MX ease of assembly to provide particularly compact Manifolds.

- » High precision
- » Low electric consumption
- » High exhaust flow
- » Modular with Series MX
- » MANIFOLD and external servo pilot supply versions available
- » Suitable for use with oxygen

C<

CAMOZZ

I

GENERAL DATA

	PROPORTIONAL PRESSURE REGULATOR	PROPORTIONAL FLOW VALVE
Construction	modular, compact, diaphragm type	modular, piston type
Materials	see material tables on the following pages	see material tables on the following pages
Ports	G1/2	G1/2
Mounting	vertical in-line, wall-mounting (by means of clamps)	vertical in-line, wall-mounting (by means of clamps)
Working pressure	0°C ÷ 50°C	0°C ÷ 50°C
Max inlet pressure	11 bar (10 bar), 4 bar (3 bar), 1.5 bar (1 bar), 8 bar (7 bar)	6 bar
Regulated pressure	0.5 ÷ 10 bar, 0.15 ÷ 3 bar, 0.05 ÷ 1 bar, 0.35 ÷ 7	-
Max servo-pilot pressure	4 bar (3 bar), 11 bar (10 bar), 1.5 bar (1 bar), 8 bar (7 bar)	4 bar (essential for the proper functioning)
Overpressure exhaust	with Relieving (standard) or without Relieving	NO
Nominal flow	see flow diagrams on the following pages	see flow diagrams on the following pages
Air specifications	filtered compressed air, non lubricated, class 7.4.4 according to ISO 8573.1 standard. If lubrication is necessary, please use only oils with maximum viscosity of 32 Cst and the version with external servo-pilot supply. The servo-pilot supply air quality class must be 7.4.4 according to ISO 8573.1 standard.	filtered compressed air, non lubricated, class 7.4.4 according to ISO 8573.1 Standard. If lubrication is necessary, please use only oils with maximum viscosity of 32 Cst and the version with external servo-pilot supply. The servo-pilot supply air quality class must be 7.4.4 according to ISO 8573.1 standard.
Pressure gauge	with built-in pressure gauge (standard) with G1/8 port	without pressure gauge
Analogical input	0-10 V DC Ripple ≤ 0.2%; 4 - 20 mA	0-10 V DC Ripple ≤ 0.2%; 4 - 20 mA
Analogical output	0.5 - 9.5 V DC [Feedback]	not relevant
Electrical supply	24 V DC ±10%	24 V DC ±10%
Electrical connection	M8 4 Pin (Male)	M8 4 Pin (Male)
Linearity	≤ ± 1% FS	±4% FS
Hysteresis	±0.5% FS	±8% FS
Repeatability	±0.5% FS	±0.35% FS
Sensibility	0.3% FS	5% FS
Protection class	IP51	IP51


CODING EXAMPLE

МХ	2	_	1/2	-		R	CV		2	0		4		-	LH	
	_		_/_									-				
MX	SERIES															
2	SIZE: 2 = G1/2															
1/2	PORTS: 1/2 = G1/2															
R	FUNCTIONING: R = pressure regulator M = Manifold pressure regulator								V = flow valve W = Manifold flow valve							
CV	COMMAND: CV = electrical command 0-10 V DC (regulator only) CA = electrical command 4-20 mA (regulator only)								EV = electrical command 0-10 V DC with external servo pilot supply EA = electrical command 4-20 mA with external servo pilot supply							
2	REGULATOR SETTING RANGE: 1 = working pressure 0 ÷ 3 bar 2 = working pressure 0 ÷ 10 bar 3 = working pressure 0 ÷ 1 bar 4 = working pressure 0 ÷ 7 bar						VALVE SETTING RANGE: 8 = low flow 9 = high flow									
0	DESIGN TYP 0 = relievin 1 = without	ig (regulator o	nly)													
4	PRESSURE GAUGE: 0 = without pressure gauge, with threaded port for gauges 2 = with built-in pressure gauge 0-6 bar (regulator only) 4 = with built-in pressure gauge 0-12 bar (regulator only)															
LH	= from le	FLOW DIRECTION: = from left to right (standard) LH = from right to left														
0X1	VERSIONS: = standard OX1 = for us		ו (in compliance א	vith ASTM G93-)3 Level E)	, FKM seals										

Further details about the assembly of a single component with fixing flanges or wall-mounting can be found in the AIR TREATMENT catalogue, section SERIES MX ASSEMBLED FRL.

Series MX-PRO proportional pressure regulator - materials


R = proportional pressure regulator M = Manifold proportional pressure regulator



PARTS	MATERIALS, standard version	MATERIALS, oxygen version				
1 = Body	Aluminium	Aluminium				
2 = Covering	Polyacetal	PBT				
3 = Valve holder plug	Polyacetal	PBT				
4 = Upper base	Aluminium	Aluminium				
5 = Lower spring	Stainless steel	Stainless steel				
6 = Diaphragm	NBR	FKM				
Seals	NBR	FKM				

Series MX-PRO proportional flow valve - materials

V = proportional flow valve W = Manifold proportional flow valve



PARTS	MATERIALS, standard version	MATERIALS, oxygen version		
1 = Body	Aluminium	Aluminium		
2 = Covering	Polyacetal	PBT		
3 = Valve holder plug	Polyacetal	РВТ		
4 = Upper base	Aluminium	Aluminium		
5 = Lower spring	Stainless steel	Stainless steel		
Seals	NBR	FKM		

SERIES MX-PRO PROPORTIONAL REGULATOR AND VALVE


Series MX-PRO proportional pressure regulator



Male connector M8 4 poles Pin 1: +24 V DC (Power supply) Pin 2: Command analogical signal 0-10 V DC or 4-20 mA Pin 3: 0 V (Ground) common also for the command signal Pin 4: Output analogical signal (according to the regulated pressure)

5 red LED 6 green LED

DRAWING NOTE: ** = in the versions with external servo pilot
supply only (MX2-1/2-REV... and MX2-1/2-REA...)



Mod.	Electrical command	Setting range	Pressure gauge
MX2-1/2-R*V1**0	0-10 V DC	0 ÷ 3 bar	without pressure gauge
MX2-1/2-R*V1**2	0-10 V DC	0 ÷ 3 bar	with built-in pressure gauge 0-6
MX2-1/2-R*V1**4	0-10 V DC	0 ÷ 3 bar	with built-in pressure gauge 0-12
MX2-1/2-R*V2**0	0-10 V DC	0 ÷ 10 bar	without pressure gauge
MX2-1/2-R*V2**2	0-10 V DC	0 ÷ 10 bar	with built-in pressure gauge 0-6
MX2-1/2-R*V2**4	0-10 V DC	0 ÷ 10 bar	with built-in pressure gauge 0-12
MX2-1/2-R*V3**0	0-10 V DC	0 ÷ 1 bar	without pressure gauge
MX2-1/2-R*V3**2	0-10 V DC	0 ÷ 1 bar	with built-in pressure gauge 0-6
MX2-1/2-R*V3**4	0-10 V DC	0 ÷ 1 bar	with built-in pressure gauge 0-12
MX2-1/2-R*V4**0	0-10 V DC	0 ÷ 7 bar	without pressure gauge
MX2-1/2-R*V4**2	0-10 V DC	0 ÷ 7 bar	with built-in pressure gauge 0-6
MX2-1/2-R*V4**4	0-10 V DC	0 ÷ 7 bar	with built-in pressure gauge 0-12
MX2-1/2-R*A1**0	4-20 mA	0 ÷ 3 bar	without pressure gauge
MX2-1/2-R*A1**2	4-20 mA	0 ÷ 3 bar	with built-in pressure gauge 0-6
MX2-1/2-R*A1**4	4-20 mA	0 ÷ 3 bar	with built-in pressure gauge 0-12
MX2-1/2-R*A2**0	4-20 mA	0 ÷ 10 bar	without pressure gauge
MX2-1/2-R*A2**2	4-20 mA	0 ÷ 10 bar	with built-in pressure gauge 0-6
MX2-1/2-R*A2**4	4-20 mA	0 ÷ 10 bar	with built-in pressure gauge 0-12
MX2-1/2-R*A3**0	4-20 mA	0 ÷ 1 bar	without pressure gauge
MX2-1/2-R*A3**2	4-20 mA	0 ÷ 1 bar	with built-in pressure gauge 0-6
MX2-1/2-R*A3**4	4-20 mA	0 ÷ 1 bar	with built-in pressure gauge 0-12
MX2-1/2-R*A4**0	4-20 mA	0 ÷ 7 bar	without pressure gauge
MX2-1/2-R*A4**2	4-20 mA	0 ÷ 7 bar	with built-in pressure gauge 0-6
MX2-1/2-R*A4**4	4-20 mA	0 ÷ 7 bar	with built-in pressure gauge 0-12
MX2-1/2-R*V1**0-OX1	0-10 V DC	0 ÷ 3 bar	without pressure gauge
MX2-1/2-R*V1**2-0X1	0-10 V DC	0 ÷ 3 bar	with built-in pressure gauge 0-6
MX2-1/2-R*V1**4-0X1	0-10 V DC	0 ÷ 3 bar	with built-in pressure gauge 0-12
MX2-1/2-R*V3**0-0X1	0-10 V DC	0 ÷ 1 bar	without pressure gauge
MX2-1/2-R*V3**2-0X1	0-10 V DC	0 ÷ 1 bar	with built-in pressure gauge 0-6
MX2-1/2-R*V3**4-0X1	0-10 V DC	0 ÷ 1 bar	with built-in pressure gauge 0-12
MX2-1/2-R*V4**0-OX1	0-10 V DC	0 ÷ 7 bar	without pressure gauge
MX2-1/2-R*V4**2-0X1	0-10 V DC	0 ÷ 7 bar	with built-in pressure gauge 0-6
MX2-1/2-R*V4**4-0X1	0-10 V DC	0 ÷ 7 bar	with built-in pressure gauge 0-12
MX2-1/2-R*A1**0-OX1	4-20 mA	0 ÷ 3 bar	without pressure gauge
MX2-1/2-R*A1**2-OX1	4-20 mA	0 ÷ 3 bar	with built-in pressure gauge 0-6
MX2-1/2-R*A1**4-0X1	4-20 mA	0 ÷ 3 bar	with built-in pressure gauge 0-12
MX2-1/2-R*A3**0-OX1	4-20 mA	0 ÷ 1 bar	without pressure gauge
MX2-1/2-R*A3**2-0X1	4-20 mA	0 ÷ 1 bar	with built-in pressure gauge 0-6
MX2-1/2-R*A3**4-OX1	4-20 mA	0 ÷ 1 bar	with built-in pressure gauge 0-12
MX2-1/2-R*A4**0-OX1	4-20 mA	0 ÷ 7 bar	without pressure gauge
MX2-1/2-R*A4**2-0X1	4-20 mA	0 ÷ 7 bar	with built-in pressure gauge 0-6
MX2-1/2-R*A4**4-0X1	4-20 mA	0 ÷ 7 bar	with built-in pressure gauge 0-12


TABLE NOTES:


* = versions with or without external pilot supply

** = versions with our without relieving

LH = add LH at the end of the code for air inlet from the right to the left

PRESSURE REGULATOR FLOW DIAGRAMS - STANDARD VERSION






Pr = Regulated pressure Q = Flow

Pa = Inlet pressure


Q = Flow Pa = Inlet pressure

EXHAUST FLOW DIAGRAM AND PNEUMATIC SYMBOLS



Pr = Regulated pressure Q = Flow

Pa = Inlet pressure



K801 = relieving, electrical command

K802 = NO relieving, electrical command

K803 = relieving, electrical command, built-in pressure gauge K804 = NO relieving, electrical command, built-in pressure gauge K809 = relieving, electrical command, ext. servo pilot supply K810 = NO reliev., electrical command, ext. servo pilot supply

K811 = reliev., el. com., built-in pr. gauge, ext. servo pilot supply

K812 = NO reliev., el. com., built-in pr. gauge, ext. servo pilot sup.

SERIES MX-PRO PROPORTIONAL REGULATOR AND VALVE


Series MX-PRO proportional pressure regulator



Male connector M8 4 poles Pin 1: +24 V DC (Power supply) Pin 2: Command analogical signal 0-10 V DC or 4-20 mA Pin 3: 0 V (Ground) common also for the command signal Pin 4: Output analogical signal (according to the regulated pressure)

5 red LED 6 green LED

DRAWING NOTE: ** = in the versions with external servo pilot supply only (MX2-1/2-REV... and MX2-1/2-REA...)



----- -----

Mod.	Electrical command	Setting range	Pressure gauge
MX2-1/2-M*V1**0	0-10 V DC	0 ÷ 3 bar	without pressure gauge
MX2-1/2-M*V1**2	0-10 V DC	0 ÷ 3 bar	with built-in pressure gauge 0-6
MX2-1/2-M*V1**4	0-10 V DC	0 ÷ 3 bar	with built-in pressure gauge 0-12
MX2-1/2-M*V2**0	0-10 V DC	0 ÷ 10 bar	without pressure gauge
MX2-1/2-M*V2**2	0-10 V DC	0 ÷ 10 bar	with built-in pressure gauge 0-6
MX2-1/2-M*V2**4	0-10 V DC	0 ÷ 10 bar	with built-in pressure gauge 0-12
MX2-1/2-M*V3**0	0-10 V DC	0 ÷ 1 bar	without pressure gauge
MX2-1/2-M*V3**2	0-10 V DC	0 ÷ 1 bar	with built-in pressure gauge 0-6
MX2-1/2-M*V3**4	0-10 V DC	0 ÷ 1 bar	with built-in pressure gauge 0-12
MX2-1/2-M*V4**0	0-10 V DC	0 ÷ 7 bar	without pressure gauge
MX2-1/2-M*V4**2	0-10 V DC	0 ÷ 7 bar	with built-in pressure gauge 0-6
MX2-1/2-M*V4**4	0-10 V DC	0 ÷ 7 bar	with built-in pressure gauge 0-12
MX2-1/2-M*A1**0	4-20 mA	0 ÷ 3 bar	without pressure gauge
MX2-1/2-M*A1**2	4-20 mA	0 ÷ 3 bar	with built-in pressure gauge 0-6
MX2-1/2-M*A1**4	4-20 mA	0 ÷ 3 bar	with built-in pressure gauge 0-12
MX2-1/2-M*A2**0	4-20 mA	0 ÷ 10 bar	without pressure gauge
MX2-1/2-M*A2**2	4-20 mA	0 ÷ 10 bar	with built-in pressure gauge 0-6
MX2-1/2-M*A2**4	4-20 mA	0 ÷ 10 bar	with built-in pressure gauge 0-0
MX2-1/2-M*A3**0	4-20 mA	0 ÷ 1 bar	without pressure gauge
MX2-1/2-M*A3**2	4-20 mA	0 ÷ 1 bar	with built-in pressure gauge 0-6
MX2-1/2-M*A3**4	4-20 mA	0 ÷ 1 bar	with built-in pressure gauge 0-12
MX2-1/2-M*A4**0	4-20 mA	0 ÷ 1 bar	without pressure gauge
MX2-1/2-M*A4**0	4-20 mA	0 ÷ 7 bar	with built-in pressure gauge 0-6
MX2-1/2-M*A4**4	4-20 mA	0 ÷ 7 bar	with built-in pressure gauge 0-12
MX2-1/2-M*V1**0-OX1	0-10 V DC	0 ÷ 7 bar	without pressure gauge
MX2-1/2-M*V1**2-0X1	0-10 V DC	0 ÷ 3 bar	with built-in pressure gauge 0-6
	0-10 V DC	0 ÷ 3 bar	
MX2-1/2-M*V1**4-0X1	0-10 V DC	0 ÷ 3 bar	with built-in pressure gauge 0-12
MX2-1/2-M*V3**0-0X1 MX2-1/2-M*V3**2-0X1	0-10 V DC	0 ÷ 1 bar	without pressure gauge with built-in pressure gauge 0-6
MX2-1/2-M*V3**4-0X1	0-10 V DC	0 ÷ 1 bar	
MX2-1/2-M*V3**4-0X1 MX2-1/2-M*V4**0-0X1	0-10 V DC	0 ÷ 7 bar	with built-in pressure gauge 0-12
	0-10 V DC	0 ÷ 7 bar	without pressure gauge with built-in pressure gauge 0-6
MX2-1/2-M*V4**2-0X1	0-10 V DC	0 ÷ 7 bar	
MX2-1/2-M*V4**4-0X1			with built-in pressure gauge 0-12
MX2-1/2-M*A1**0-OX1	4-20 mA	0 ÷ 3 bar	without pressure gauge
MX2-1/2-M*A1**2-OX1	4-20 mA	0 ÷ 3 bar	with built-in pressure gauge 0-6
MX2-1/2-M*A1**4-OX1	4-20 mA	0 ÷ 3 bar	with built-in pressure gauge 0-12
MX2-1/2-M*A3**0-0X1	4-20 mA	0 ÷ 1 bar	without pressure gauge
MX2-1/2-M*A3**2-0X1	4-20 mA	0 ÷ 1 bar	with built-in pressure gauge 0-6
MX2-1/2-M*A3**4-0X1	4-20 mA	0 ÷ 1 bar	with built-in pressure gauge 0-12
MX2-1/2-M*A4**0-0X1	4-20 mA	0 ÷ 7 bar	without pressure gauge
MX2-1/2-M*A4**2-0X1	4-20 mA	0 ÷ 7 bar	with built-in pressure gauge 0-6
MX2-1/2-M*A4**4-OX1	4-20 mA	0 ÷ 7 bar	with built-in pressure gauge 0-12


TABLE NOTES:

* = versions with or without external pilot supply

** = versions with our without relieving

LH = add LH at the end of the code for air inlet from the right to the left


PRESSURE REGULATOR FLOW DIAGRAMS - MANIFOLD VERSION



Pa = Inlet pressure

Pa = Inlet pressure


EXHAUST FLOW DIAGRAM - MANIFOLD VERSION




Pr = Regulated pressure Q = Flow


Pa = Inlet pressure

PNEUMATIC SYMBOLS - MANIFOLD VERSION





K808 = MANIFOLD reg., NO relieving, electrical command and built-in pressure gauge





- K813 = MANIFOLD reg., relieving, electrical command, and external servo pilot supply
- K814 = MANIFOLD reg., NO relieving, electrical command, and external servo pilot supply
- K815 = MANIFOLD reg., relieving, electrical command, built-in pressure gauge and external servo pilot supply
- K816 = MANIFOLD reg., NO relieving, electrical command, built-in pressure gauge and external servo pilot supply


Series MX-PRO proportional flow valve



Male connector M8 4 poles Pin 1: +24 V DC (Power supply) Pin 2: Command analogical signal 0-10 V DC or 4-20 mA Pin 3: 0 V (Ground) common also for the command signal Pin 4: Output analogical signal (according to the regulated pressure) 5 red LED











6 green LED

Mod.	Electrical command	Setting range
MX2-1/2-VEV810	0-10 V DC	low flow
MX2-1/2-VEA810	4-20 mA	low flow
MX2-1/2-VEV910	0-10 V DC	high flow
MX2-1/2-VEA910	4-20 mA	high flow
MX2-1/2-VEV810-LH	0-10 V DC	low flow
MX2-1/2-VEA810-LH	4-20 mA	low flow
MX2-1/2-VEV910-LH	0-10 V DC	high flow
MX2-1/2-VEA910-LH	4-20 mA	high flow
MX2-1/2-VEV8100X1	0-10 V DC	low flow
MX2-1/2-VEA8100X1	4-20 mA	low flow
MX2-1/2-VEV9100X1	0-10 V DC	high flow
MX2-1/2-VEA9100X1	4-20 mA	high flow
MX2-1/2-VEV810-LHOX1	0-10 V DC	low flow
MX2-1/2-VEA810-LHOX1	4-20 mA	low flow
MX2-1/2-VEV910-LHOX1	0-10 V DC	high flow
MX2-1/2-VEA910-LHOX1	4-20 mA	high flow

SERIES MX-PRO PROPORTIONAL REGULATOR AND VALVE

VALVE FLOW DIAGRAMS





Low flow version

Q (Nl/min) = flow FS% = full scale command signal

High flow

Q (Nl/min) = flow FS% = full scale command signal





Series MX-PRO Manifold proportional flow valve





Male connector M8 4 poles Pin 1: +24 V DC (Power supply) Pin 2: Command analogical signal 0-10 V DC or 4-20 mA Pin 3: 0 V (Ground) common also for the command signal Pin 4: Output analogical signal (according to the regulated pressure)

5 red LED 6 green LED










Mod.	Electrical command	Setting range
MX2-1/2-WEV810	0-10 V DC	low flow
MX2-1/2-WEA810	4-20 mA	low flow
MX2-1/2-WEV910	0-10 V DC	high flow
MX2-1/2-WEA910	4-20 mA	high flow
MX2-1/2-WEV810-LH	0-10 V DC	low flow
MX2-1/2-WEA810-LH	4-20 mA	low flow
MX2-1/2-WEV910-LH	0-10 V DC	high flow
MX2-1/2-WEA910-LH	4-20 mA	high flow
MX2-1/2-WEV8100X1	0-10 V DC	low flow
MX2-1/2-WEA8100X1	4-20 mA	low flow
MX2-1/2-WEV9100X1	0-10 V DC	high flow
MX2-1/2-WEA9100X1	4-20 mA	high flow
MX2-1/2-WEV810-LHOX1	0-10 V DC	low flow
MX2-1/2-WEA810-LHOX1	4-20 mA	low flow
MX2-1/2-WEV910-LHOX1	0-10 V DC	high flow
MX2-1/2-WEA910-LHOX1	4-20 mA	high flow

VALVE FLOW DIAGRAMS - MANIFOLD VERSION




Q (Nl/min) = flow FS% = full scale command signal

5

Q (Nl/min) = flow FS% = full scale command signal

Flow characteristic curve of a proportional valve

Q% = flow FS% = full scale command signal




Valve maximum flow and response times

Maximum flow according to the inlet pressure

DIAGRAM LEGEND:

Q = flow (Nl/min) P = inlet pressure (bar)



Pin	Туре		Flow at steady speed [Nl/min]	Command [V]]	Load respo	nse time (ms)		Exhaust réponse time (ms)			
					0-10%	0-50%	0-90%	0-99%	0-10%	0-50%	0-90%	0-99%
2 bar	Low flow	Standard	915	6	351	452.4	967.2	6240	171.6	284.7	487.5	624
		Manifold	1000	6.3	327.6	421.2	951.6	6162	249.6	366.6	577.2	780
	High flow	Standard	960	4.7	331.5	444.6	1279.2	6942	245.7	329.16	526.5	702
		Manifold	960	4.2	313	420	1156	9700	200	340	540	800
4 bar	Low flow	Standard	952	5.4	319.8	436.8	1029.6	7410	187.2	304.2	491.4	624
		Manifold	925	5.3	284.7	408.72	1474.2	6240	237.9	370.5	557.7	897
	High flow	Standard	970	4.4	279.24	429	1177.8	7878	225	351	526.5	741
	-	Manifold	940	3.8	230	400	1680	8500	175	360	580	900
						Set flow: abo	out 1000 Nl/min					


Rapid clamp kit

The kit MX2-X is supplied with: 1 rapid clamp, 1 O-ring OR 3125 *, 2 exagonal nuts M5, 2 screws M5x69. The kit MX2-Z is supplied with:

1 rapid clamp, 1 O-ring OR 3125 *, 1 exagonal nut M5, 1 screw M5x69, 1 screw M5x85 for wall fixing.

* it can be ordered separately (cod. 160-39-11/19)

Materials: technopolymer clamp, NBR O-ring, zinc-plated steel nuts and screws.



DIMENSIO	NS								
Mod.	А	В	С	D	E	F	G	Н	L
MX2-X	5.2	12	46	14	73.5	37.5	70.5	37	-

14

Rapid clamp kit with wall fixing brackets

46

12



5.2

MX2-Z

The kit MX2-Y is supplied with: 1 wall rapid clamp, 1 O-ring OR 3125 **, 2 exagonal nuts, 2 screws M5x69.

73.5

37.5


70.5

37

14

** it can be separately ordered (cod. 160-39-11/19)

Materials: technopolymer clamp, NBR O-ring, zinc-plated steel nuts and screws.



М

M5

Notes

kit with wall fixing screw


Mod.	Α	В	С	D	Е	F	G	Н	1	L	М	Ν	0	Р	R
MX2-Y	5,2	12	46	14	73,5	32,5	70,5	37	70,5	103	12	6,5	42	152	4

Terminal flanges (IN/OUT)



The kit is supplied with: - 1 flange INLET side - 1 flange OUTLET side

Materials: painted aluminium flanges.



Mod.	Α	В	C	D	E	G
MX2-1/2-FL	G1/2	50	26,5	63,5	17	11

Rapid clamps kit + flanges




Mod.	The kit is supplied with:
MX2-1/2-HH	1x MX2-1/2-FL + 2x MX2-X
MX2-1/2-JJ	1x MX2-1/2-FL + 2x MX2-Z


Rapid clamps kit with wall fixing brackets + flanges



Mod.	The kit is supplied with:
MX2-1/2-KK	1x MX2-1/2-FL + 2x MX2-Y

Block for pressure gauge fixing






Mod.	Α	В	L	М	Р	U	SW
MX2-R26/1-P	28	28	16.5	5	M3X7	1/8	5

O-ring for assembling






Mod.	0-ring	For assembly	
160-39-11/19	OR 3125	MX2	

Circular M8 4-pole connectors, Female



With PU sheathing, non shielded cable. Protection class: IP65



3 0 0 1

Mod.	Type of connector	Cable length (m)
CS-DF04EG-E200	straight	2
CS-DF04EG-E500	straight	5
CS-DR04EG-E200	right angle (90 degrees)	2
CS-DR04EG-E500	right angle (90 degrees)	5